### Facility Summary in VALLEY County in the City of FORT PECK

**Location:** US ARMY CORPS OF ENGINEERS FORT PECK

Sys Fac ID: 53-04612

JUDITH RD

FORT PECK, MT 59223 VALLEY Operating Permit Renewal Date: 8/28/2018

**Contact:** Tom Hansen, (406) 526-3431

Owners/Operators: US Army Corps of Engineers Fort Peck, Owner (406)-526-3411 PO BOX 208

FORT PECK MT 59223-0208

Last Inspected On: 6/23/2015

Tom Hansen, UST Class A Operator Tom Hansen, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	AST Sump Tightness Secondary Option	Secondary Option	Spill Protected	
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	25	6/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
2156			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		6/23/2015	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	MLLD Line Tightness Testing	
2,500		6/23/2015	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
7	25	6/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
2154			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		6/23/2015	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	MLLD Line Tightness Testing	
9,000		6/23/2015	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
8	25	6/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
2155			Double-Walled	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		6/23/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	MLLD Line Tightness Testing	
2,500		6/23/2015	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Location: NAKODA TRAILSTOP Sys Fac ID: 56-13890

MAIN ST & 2ND ST Last Inspected On: 6/17/1999

FRAZER, MT 59225 VALLEY Operating Permit Renewal Date:

Contact: Anthony Runsthrough, (406) 768-3480

Owners/Operators: Fort Peck Assiniboine & Sioux Tribes, Owner (406)-768-5155 501 MEDICINE BEAR ROAD

POPLAR MT 59255-1027

Julie Flynn, Operator PO BOX 342 FRAZER MT 59225-0342

Anita Trice, UST Class A Operator

Anita Trice, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	18	12/1/1997	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
			None	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Tank Tightness Testing, Automatic Tank Gauging 0.1, Manual Interstitial Monitor	Continuous Interstitial Monitor	
1,000					
2	18	12/1/1997	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
			None	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline			Tank Tightness Testing, Automatic Tank Gauging 0.1, Manual Interstitial Monitor	Continuous Interstitial Monitor	
2,000					

Location: FARMERS UNION OIL DBA AGLAND COOP Sys Fac ID: 53-03160

430 1ST AVE N

GLASGOW, MT 59230 VALLEY

Operating Permit Renewal Date: 1/30/2019

Last Inspected On: 11/23/2015

**Contact:** Brent Bacon, (406) 785-7272

Owners/Operators: Farmers Union Oil DBA Agland Coop, Owner (406)-228-4641 430 1ST AVE NORTH

GLASGOW MT 59230

Brent Bacon, Operator (406)-785-7272 810 FRONT STREET

NASHUA MT 59248

Brent Bacon, UST Class A Operator Kory Hentges, UST Class A Operator Tanner Trower, UST Class A Operator Monica Turnburke, UST Class A Operator Antonio Alvernaz, UST Class B Operator Kent Cromwell, UST Class B Operator Kory Hentges, UST Class B Operator Steven Long, UST Class B Operator Keith Meche, UST Class B Operator Michael Pallvoda, UST Class B Operator Allen Richard, UST Class B Operator Tanner Trower, UST Class B Operator Bruce Unger, UST Class B Operator Allen Richard, UST Class B Global Operator Weston Smith, UST Class B Global Operator Monica Turnburke, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	24	5/1/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
1574		10/26/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		10/16/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

**Location:** FARMERS UNION OIL DBA AGLAND COOP

Sys Fac ID: 53-03160

430 1ST AVE N

GLASGOW, MT 59230 VALLEY Operating Permit Renewal Date: 1/30/2019

**Contact:** Brent Bacon, (406) 785-7272

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	24	5/1/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
1575		10/26/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		10/16/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
7	24	5/1/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
1577		10/26/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		10/16/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
6,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
8	24	5/1/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
1578		10/26/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Safe Suction	Galvanic
Diesel		10/16/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
2,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
9	24	5/1/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
1576		10/26/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasohol/Ethanol		10/16/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Report Generation Date: 3/1/2016

Last Inspected On: 11/23/2015

**Location**: FARMERS UNION OIL DBA AGLAND COOP

Sys Fac ID: 53-03160

430 1ST AVE N

GLASGOW, MT 59230 VALLEY Operating Permit Renewal Date: 1/30/2019

Last Inspected On: 11/23/2015

**Contact:** Brent Bacon, (406) 785-7272

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
10	03	10/1/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
5391		10/26/2012	Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
20,000		10/26/2012	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor, Not Listed	Yes

Location: GLASGOW INTERNATIONAL AIRPORT Sys Fac ID: 53-03271

100 AIRPORT RD

GLASGOW, MT 59230 VALLEY

**Operating Permit Renewal Date:** 

Last Inspected On: 10/27/2015

**Contact:** Steve Stanley, (406) 228-4023

(406)-228-8221 501 COURT SQ STE 14

GLASGOW MT 59230-2415

Owners/Operators: Valley County Airport Commission, Owner

Anthony Hebert, UST Class A Operator Robert Lipscomb, UST Class A Operator Lucas Locke, UST Class A Operator

Christopher Mortensen, UST Class A Operator

Steve Stanley, UST Class A Operator Robert Lipscomb, UST Class B Operator Lucas Locke, UST Class B Operator Steve Stanley, UST Class B Operator

Anthony Hebert, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	36	1/1/1980	Cathodically Protected Steel	Steel	High Level Alarm
2726			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/22/2013	Stat. Inventory Reconcilitation	Stat. Inventory Reconcilitation	
12,000		8/9/2006			
2	36	1/1/1980	Cathodically Protected Steel	Steel	High Level Alarm
2726			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		5/22/2013	Stat. Inventory Reconcilitation	Stat. Inventory Reconcilitation	
12,000		8/9/2006			
3	34	4/7/1981	Cathodically Protected Steel	No Piping	High Level Alarm
2727			Lined Interior/Impressed Current	None	Yes
Currently in Use		7/1/2008	Not Required	U.S. Suction	Impressed Current
Jet Fuel		5/22/2013	Stat. Inventory Reconcilitation	Stat. Inventory Reconcilitation	
12,000		8/9/2006			

Report Generation Date: 3/1/2016

GLASGOW INTERNATIONAL AIRPORT **Sys Fac ID:** 53-03271 Location:

100 AIRPORT RD

Last Inspected On: 10/27/2015 GLASGOW, MT 59230 VALLEY **Operating Permit Renewal Date:** 

Steve Stanley, (406) 228-4023 Contact:

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	34	4/7/1981	Cathodically Protected Steel	No Piping	High Level Alarm
2727			Lined Interior/Impressed Current	None	Yes
Currently in Use		7/1/2008	Not Required	U.S. Suction	Impressed Current
Jet Fuel		5/22/2013	Stat. Inventory Reconcilitation	Stat. Inventory Reconcilitation	
12,000		8/9/2006			

Location: FRANCES MAHON DEACONESS HOSPITAL **Sys Fac ID:** 53-05192

621 3RD ST S

Last Inspected On: 6/23/2014 GLASGOW, MT 59230 Operating Permit Renewal Date: 11/6/2017 **VALLEY** 

John Fontaine, (406) 228-4351 Contact:

Owners/Operators: Frances Mahon Deaconess Hospital, Owner 621 3RD ST S (406)-228-4351

GLASGOW MT 59230-2604

Trinity Cook, UST Class A Operator Patrick Menge, UST Class A Operator David Nixdorf, UST Class A Operator Walter L Adams, UST Class B Operator Daivd Bradley, UST Class B Operator Jeff Damboise, UST Class B Operator Gregory Eldridge, UST Class B Operator Richard Trathen, UST Class B Operator Patrick Menge, UST Class B Global Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	ST Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	20	10/1/1995	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1118			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Galvanic
Diesel		5/22/2013	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Deferred	
4,000			TLS-300 , Veeder Root	Continuous Interstitial Monitor	
3	20	10/1/1995	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1119			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Galvanic
Diesel		5/22/2013	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Deferred	
2,000			TLS-300 , Veeder Root	Continuous Interstitial Monitor	

Location: EZZIE'S MIDTOWN Sys Fac ID: 53-05709

(406)-654-2331

204 1ST AVE N Last Inspected On: 1/1/2014

GLASGOW, MT 59230 VALLEY Operating Permit Renewal Date: 4/4/2017

**Contact:** David Skiff, (406) 654-2331

MALTA MT 59538-9640

PO BOX 1770

David Skiff, Operator (406)-654-2331 PO BOX 467

MALTA MT 59538-0467

Jody Faul, UST Class A Operator Jody Faul, UST Class B Operator Jennifer Fischer, UST Class B Operator

Owners/Operators: EZZIES WHOLESALE INC, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	15	6/1/2000	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4201			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		11/9/2010	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
6,000		6/14/2013			
6	15	6/1/2000	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4202			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		11/9/2010	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
12,000		6/14/2013			

Location: TRAILSIDE GENERAL STORE GLASGOW Sys Fac ID: 53-07787

54271 HWY 2 E Last Inspected On: 3/23/2015

GLASGOW, MT 59230 VALLEY Operating Permit Renewal Date:

Contact: Wayne Waarvik JR, (406) 263-1477

#### Owners/Operators:

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	24	9/9/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	
3873			None	None	Yes
Temporarily Out of Use		9/9/2001	Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline		3/23/2015	Tank Tightness Testing, Inventory Reconciliation	MLLD Line Tightness Testing	
10,000					
4	24	9/9/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	
3874			None	None	Yes
Temporarily Out of Use		9/9/2001	Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline		3/23/2015	Tank Tightness Testing, Inventory Reconciliation	MLLD Line Tightness Testing	
10,000					

LAKERIDGE MOTEL & TACKLE INC Location: **Sys Fac ID:** 53-08383

Last Inspected On: 2/3/2016 6004 MT HIGHWAY 24 S HC 71 BOX 1660

GLASGOW, MT 59230 Operating Permit Renewal Date: 5/4/2019 VALLEY

Gene Moore, (406) 526-3597 Contact:

Owners/Operators: Gene Moore, Owner 6004 MT HIGHWAY 24 S

(406)-526-3597 GLASGOW MT 59230-8822

Gene Moore, UST Class A Operator Gene Moore, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	18	5/15/1997	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1509			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		1/21/2013	Manual Interstitial Monitor	Deferred	
4,000					
6	18	5/15/1997	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1510			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		1/21/2013	Manual Interstitial Monitor	Deferred	
2,000					

Location: **HOLIDAY STATIONSTORE 281 Sys Fac ID:** 53-09712

108 1ST AVE N

**Operating Permit Renewal Date:** 10/1/2017 GLASGOW, MT 59230 VALLEY

Bruce Anthony, (952) 830-8899 Contact:

Owners/Operators: Rocky Mountain Oil Co Inc, Owner ATTN: ENVIRONMENTAL DIRECTOR

(952)-830-8899 PO BOX 1224

MINNEAPOLIS MN 55437-1123

Last Inspected On: 6/23/2014

Stephen Reckinger, UST Class A Operator Dean Townsend, UST Class A Operator Ronald VanDenBroeke, UST Class A Operator

Craig Robbins, UST Class B Operator

Stephen Reckinger, UST Class B Global Operator Travis Struckman, UST Class B Global Operator Dean Townsend, UST Class B Global Operator

Tank Id Tag Number	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
	AST	Γ Sump Tightness Secondary Option	Secondary Option	Spill Protected	
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	26	8/1/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4431			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current, Galvanic
Gasoline		4/30/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
8,000		4/25/2014	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	29	3/1/1986	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4432			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		4/30/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
12,000		4/27/2014	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
5	27	4/15/1988	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4433			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		4/30/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
10,000		4/21/2014	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

**Location:** EZZIES WHOLESALE GLASGOW **Sys Fac ID:** 53-10475

1330 US HIGHWAY 2 W

GLASGOW, MT 59230 VALLEY Operating Permit Renewal Date: 3/24/2018

Contact: Lary Poulton, (406) 228-2713

Owners/Operators: EZZIES WHOLESALE INC, Owner (406)-654-2331 PO BOX 1770

MALTA MT 59538-9640

Last Inspected On: 11/26/2014

David Skiff, UST Class A Operator Brandon Hoerster, UST Class B Operator Jarid Jensen, UST Class B Operator David Skiff, UST Class B Operator

Brandon Hoerster, UST Class B Global Operator David Skiff, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
7	13	11/21/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4758			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000					
8	13	11/21/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4759			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
6,000					
9	13	11/21/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4760			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
6,000					

Location: EZZIES WHOLESALE GLASGOW

**Sys Fac ID**: 53-10475

1330 US HIGHWAY 2 W

Last Inspected On: 11/26/2014

GLASGOW, MT 59230 VALLEY

**Operating Permit Renewal Date:** 3/24/2018

**Contact:** Lary Poulton, (406) 228-2713

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
10	13	11/21/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4761			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
8,000					
11	13	11/21/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4762			None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Safe Suction	Not Applicable
Other			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
4,000					
12	13	11/21/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4763			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
10,000					
13	13	11/21/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4764			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
20,000					
14	13	11/21/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4765			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
30,000					

FARMERS UNION OIL CO NASHUA **Sys Fac ID:** 53-10461 Location:

810 MAIN ST

Brent Bacon, (406) 746-3311

Contact:

Last Inspected On: 5/14/2015

**Operating Permit Renewal Date:** 8/7/2018 NASHUA, MT 59248 VALLEY

Owners/Operators: Farmers Union Oil Co Nashua, Owner **PO BOX 108** (406)-746-3311

NASHUA MT 59248-0108

Brent Bacon, UST Class A Operator James Merideth, UST Class A Operator Monica Turnburke, UST Class A Operator Steven Long, UST Class B Operator Keith Meche, UST Class B Operator James Merideth, UST Class B Operator Michael Pallvoda, UST Class B Operator Allen Richard, UST Class B Operator Bruce Unger, UST Class B Operator

James Merideth, UST Class B Global Operator Allen Richard, UST Class B Global Operator Monica Turnburke, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	25	3/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
937			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		7/7/2011	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Not Listed	
2,000			Gilbarco EMC Basic , Gilbarco		
6	25	3/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
938			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		7/7/2011	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Not Listed	
4,000			Gilbarco EMC Basic , Gilbarco		

Location: FARMERS UNION OIL CO NASHUA

**Sys Fac ID:** 53-10461

810 MAIN ST

Last Inspected On: 5/14/2015

NASHUA, MT 59248 VALLEY

**Operating Permit Renewal Date:** 8/7/2018

**Contact:** Brent Bacon, (406) 746-3311

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control Tank/Pipe CP Line Tightness	Catastrophic L.D. Type 3.0 Tank Detection ATG Type	Piping Type	CP Met Types Vapor Recovery Energy Act
Product				Primary Pipe Detection	
Capacity				Secondary Pipe Detection	
7	25	3/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
939			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		7/7/2011	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Not Listed	
4,000			Gilbarco EMC Basic , Gilbarco		
8	25	3/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
940			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		7/7/2011	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Not Listed	
4,000			Gilbarco EMC Basic , Gilbarco		

Location: PRO COOP OPHEIM Sys Fac ID: 53-07814

45 SOUTH MAIN Last Inspected On: 11/5/2014

OPHEIM, MT 59250 VALLEY Operating Permit Renewal Date: 2/12/2018

Contact: Tim Stenglein, (406) 762-3231

Owners/Operators: Pro Coop Opheim, Owner (406)-762-3231 PO BOX 167

OPHEIM MT 59250-0167

Myron Redfield, UST Class A Operator Timothy Stenglein, UST Class A Operator Myron Redfield, UST Class B Operator Timothy Stenglein, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	8/1/1993	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1821			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasohol/Ethanol		11/5/2014	Manual Interstitial Monitor	Deferred	
3,700					
2	22	8/1/1993	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1822			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		11/5/2014	Manual Interstitial Monitor	Deferred	
2,300					
3	22	8/1/1993	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1820			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		11/5/2014	Manual Interstitial Monitor	Deferred	
2,300					

Location: PRO COOP OPHEIM Sys Fac ID: 53-07814

45 SOUTH MAIN Last Inspected On: 11/5/2014

OPHEIM, MT 59250 VALLEY Operating Permit Renewal Date: 2/12/2018

**Contact:** Tim Stenglein, (406) 762-3231

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Tank/Pipe CP	Catastrophic L.D. Type 3.0 Tank Detection ATG Type	Piping Type Primary Pipe Detection Secondary Pipe Detection	CP Met Types Vapor Recovery Energy Act
Product					
Capacity					
7	22	8/1/1993	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1823			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		11/5/2014	Manual Interstitial Monitor	Deferred	
3.700					

## Facility Summary in VALLEY County in the City of SAINT MARIE

Location: MT AVIATION RESEARCH BLDG CO BLDG 649A Sys Fac ID: 53-12774

BLDG 649A Last Inspected On: 2/4/2016

SAINT MARIE, MT 59231 VALLEY Operating Permit Renewal Date: 6/8/2019

Contact: Mary Armstrong, (406) 524-3777

Owners/Operators: Montana Aviation Research Co, Owner (406)-524-3777 PO BOX 831

GLASGOW MT 59230-0831

Lynn Blatter, UST Class A Operator
Brian Mix, UST Class A Operator
Preston Murch, UST Class A Operator
Michael Myrick, UST Class A Operator
Michael Nieskens, UST Class A Operator
Kevin Wersal, UST Class A Operator
Darcel Wesen, UST Class A Operator
Brian Mix, UST Class B Operator
Preston Murch, UST Class B Operator
Michael Myrick, UST Class B Operator
Michael Nieskens, UST Class B Operator
Kevin Wersal, UST Class B Operator
Darcel Wesen, UST Class B Operator
Lynn Blatter, UST Class B Global Operator
Michael Nieskens, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	22	1/1/1994	Bare Steel	Fiberglass Reinforced Plastic	
2975	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Jet Fuel			Automatic Tank Gauging 0.2, Deferred	Continuous Interstitial Monitor	
50,000			TLS-350/Gilbarco EMC , Veeder Root		
5	22	1/1/1994	Bare Steel	Fiberglass Reinforced Plastic	
2976	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Jet Fuel			Automatic Tank Gauging 0.2, Deferred	Continuous Interstitial Monitor	
50,000			TLS-350/Gilbarco EMC , Veeder Root		